




## Cas Interface 2 – Xtreme receiver connection


www.duolabs.com – all rights reserved

Here comes the Xtreme connection for Cas Interface 2.

You have to build the Slow Down board because the Cas 2 signals might be too fast for your Xtreme receiver. In this case and only in this case the Slow Down board must be done.



Pin 16 - Cas Interface 2 Connector



Slow Down Circuit for Xtreme receivers Only!!

U1,U2 = 74HC04  
R1 = 100 Ohm  
R2 = 10K Ohm